FINAL REPORT APRIL 1997

REPORT NO. 96-48


ENVIRONMENTAL MONITORING
OF M1A1 TANKS IN
SOUTH KOREA, HUNGARY, AND
FORT STEWART, GA

19971112 040

Prepared for:

Distribution Unlimited

U.S. Army Armament Research, Development, and Engineering Center
ATTN: AMSTA-AR-QAC-T
Picatinny Arsenal, NJ 07806-5000





VALIDATION ENGINEERING DIVISION SAVANNA, ILLINOIS 61074-9639

AVAILABILITY NOTICE

A copy of this report will be furnished each attendee on automatic distribution. Additional copies or authority for reprinting may be obtained by written request from Director, U.S. Army Defense Ammunition Center, ATTN: SIOAC-DEV, Savanna, IL 61074-9639.

DISTRIBUTION INSTRUCTIONS

Destroy this report when no longer needed. Do not return.

Citation of trade names in this report does not constitute an official endorsement.

The information contained herein will not be used for advertising purposes.

UNCLASSIFIED SECURITY CLASSIFICATION OF THIS PAGE

REPORT DOCUMENTATION PAGE						n Approved B No. 0704-0188
1a. REPORT SECURITY CLASSIFICATION	1b. RESTRICTIVE MARKINGS					
UNCLASSIFIED 2a. SECURITY CLASSIFICATION AUTHORITY		3. DISTRIBUTION / AVAILABILITY OF REPORT				
2b. DECLASSIFICATION / DOWNGRADING SCHEDULE	UNLIMITED					
4. PERFORMING ORGANIZATION REPORT NUMBER(S)	5. MONITORING ORGANIZATION REPORT NUMBER(S)					
96-48						
6a. NAME OF PERFORMING ORGANIZATION U.S. Army Defense	7a. NAME OF MONITORING ORGANIZATION					
Ammunition Center	SIOAC-DEV					
6c. ADDRESS (City, State, and ZIP Code) ATTN: SIOAC-DEV		7b. ADDRESS (Ci	ty, State, and ZIP Co	de)		
Savanna, IL. 61074-9639 8a. NAME OF FUNDING / SPONSORING ORGANIZATION	8b. OFFICE SYMBOL (if applicable)	9. PROCUREMENT INSTRUMENT IDENTIFICATION NUMBER				
Defense Ammunition Logistics Activity	AMSTA-AR-AI					
8c. ADDRESS (City, State, and ZIP Code)		10. SOURCE OF FUNDING NUMBERS				
ATTN: AMSTA-AR-AL		PROGRAM ELEMENT NO.	PROJECT NO.	TASK NO		WORK UNIT ACCESSION NO.
Picatinny Arsenal, NJ 07806-5000						
11. TITLE (Include Security Classification) Environmental Monitoring of M1A1	Tanks in South K	orea, Hungary	, and Fort Ste	wart, G	A	
12. PERSONAL AUTHOR(S)						
Bradley J. Haas						
13a. TYPE OF REPORT 13b. TIME COVER	ED	14. DATE OF REP	ORT (Year, Month, L	Day)	15. PAGE	COUNT
Final FROM	то	1997 A	April			
16. SUPPLEMENTARY NOTATION						
17. COSATI CODES	18. SUBJECT TERMS (Continue on reverse	if necessary and ide	ntify by blo	ck numbe	er)
FIELD GROUP SUB-GROUP						
19. ABSTRACT (Continue on reverse if necessary and identification)	tify by block number)					
The U.S. Army Defense Ammur was tasked by U. S. Army Armament temperature and humidity data of the instrumented in South Korea and Hun contains test results of the tanks monit	Research, Develor ammunition storal gary and six tank	opment and Enge racks of Mass were instrun	ngineering Cer 1A1 tanks. For mented in Ft. S	nter (AF our tank	RDEC)	to obtain
20. DISTRIBUTION / AVAILABILITY OF ABSTRACT		21. ABSTRACT SE	CURITY CLASSIFIC	ATION		
	DTIC USERS	21. ABSTRACT SECURITY CLASSIFICATION				
XXUNCLASSIFIED/UNLIMITED SAME AS RPT. 22a. NAME OF RESPONSIBLE INDIVIDUAL	UNCLASSIFIED 22b. TELEPHONE (Include Area Code) 22c. OFFICE SYMBOL			ICE SYMBOL		
JEROME H. KROHN	815-273-	8929	SIOAC-DEV			

U.S. ARMY DEFENSE AMMUNITION CENTER VALIDATION ENGINEERING DIVISION SAVANNA, IL 61074-9639

REPORT NO. 96-48

ENVIRONMENTAL MONITORING OF M1A1 TANKS IN SOUTH KOREA, HUNGARY, AND FORT STEWART, GA

TABLE OF CONTENTS

PART	PAGE NO.
1. INTRODUCTION	1-1
A. BACKGROUND	1-1
B. AUTHORITY	1-1
C. OBJECTIVE	1-1
D. CONCLUSION	1-1
2. ATTENDEES	2-1
3. TEST PROCEDURES	3-1
4. TEST RESULTS	4-1
5. PHOTOGRAPHS.	5-1
6. GRAPHS	6-1

INTRODUCTION

- A. <u>BACKGROUND</u>. The U.S. Army Defense Ammunition Center (DAC), Validation Engineering Division (SIOAC-DEV), was tasked by U.S. Army Armament Research, Development and Engineering Center (ARDEC) to monitor ammunition storage conditions inside M1A1 tanks located in South Korea, Hungary, and Ft. Stewart, GA. This report contains test results of data obtained from June-December 1996.
- B. <u>AUTHORITY</u>. The test was accomplished IAW mission responsibilities delegated by U.S. Army Armament Munitions and Chemical Command (AMCCOM), Rock Island, IL. Reference is made to the following:
- 1. Change 4, 4 October 1974, to AR740-1, 23 April 1973, Storage and Supply Activity Operation.
 - 2. AMCCOM-R, 10-17, Mission and Major Functions of USADACS, 13 January 1986.
- C. <u>OBJECTIVE</u>. The objective of the instrumentation was to obtain temperature and humidity data in the ammunition storage compartments of deployed tanks. U.S. Army Armament Research, Development and Engineering Center will apply the data obtained to provide information concerning chamberability and swelling of two designs of bourrelets.
- D. <u>CONCLUSION</u>. The temperature and humidity in the stowage compartments of the tanks generally maintained higher temperature levels than ambient conditions provided. The temperature and humidity conditions of the semiready and ready storage compartments were similar. Hull storage experienced similar temperature conditions to the semiready and ready storage areas. The standing water, being common in the hull storage area, contributed to the generally higher hull storage area humidity than the semiready and ready storage areas.

JUNE - DECEMBER 1996

ATTENDEES

Bradley J. Haas Director

Mechanical Engineer U.S Army Defense Ammunition Center

DSN 585-8336 ATTN: SIOAC-DEV 815-273-8336 3700 Army Depot Road

Savanna, IL 61074-9639

William R. Meyer Director

General Engineer U.S Army Defense Ammunition Center

DSN 585-8090 ATTN: SIOAC-DEV 815-273-8090 3700 Army Depot Road Savanna, IL 61074-9639

Quinn D. Hartman Director

General Engineer U.S. Army Defense Ammunition Center

DSN 585-8992 ATTN: SIOAC-DEV 815-273-8992 3700 Army Depot Road Savanna, IL 61074-9639

David V. Valant Director

Electronics Technician U.S. Army Defense Ammunition Center

DSN 585-8988 ATTN: SIOAC-DEV 815-273-8988 3700 Army Depot Road Savanna, IL 61074-9639

Richard O. Schubert Commander

201-724-3519

DSN 880-7597 U.S. Army Armament Research, Development

201-724-7597 and Engineering Center

ATTN: AMSTA-AR-QAC-T, B-62 Picatinny Arsenal, NJ 07806-5000

ATTN: AMCPM-TMA

MAJ Steve Thorsen Office of Project Manager for DSN 880-3519 Tank Main Armament Systems

Picatinny Arsenal, NJ 07806-5000

Christopher A. DeLima DSN 880-3782 201-724-3782

Commander
U.S. Army Armament Research, Development and Engineering Center
ATTN: AMSTA-AR-QAC-T
Picatinny Arsenal, NJ 07806-5000

TEST PROCEDURE

M1A1 tanks were instrumented at the following three sites: Fort Stewart, GA; Taborfalva Training Area, Hungary; and Camp Gary Owen, South Korea. Each tank was instrumented with three ACR data loggers. One data logger was placed in the tank ready rack, one data logger in the semiready rack, and one data logger in the hull stowage compartment. These data loggers collected temperature and humidity readings for these locations. The instrumented tanks continued to be used in normal operations, including maintenance. Additionally, a weather station was assembled at each location to record ambient conditions.

At the Fort Stewart site, six tanks were instrumented as described above. Readings were recorded every 10 minutes, 30 May - 1 November 1996. A weather station was operated onsite.

At Taborfalva Training Area, Hungary, four tanks were instrumented as described above. The data loggers recorded readings every 10 minutes. The initial data loggers were installed 24 June 1996. The program concluded 16 December 1996. A weather station was operated onsite.

The South Korea site had four tanks instrumented, each with three data loggers. Camp Gary Owen is located approximately 50 km east-northeast of Seoul and 325 km north of Taegu. The data loggers recorded temperature and humidity data every 30 minutes. The data loggers were initially installed 6 June 1996, with the program concluding 20 December 1996. The South Korea weather station was positioned at Ammunition Depot 2 (AD-2), located approximately 40 km southeast of Taegu.

TEST RESULTS

Six M1A1 tanks were instrumented at Fort Stewart from 30 May - 31 October 1996. The ambient temperature during this timeframe ranged from 44 degrees Fahrenheit to 101 degrees Fahrenheit. The maximum semiready storage temperature of 112 degrees Fahrenheit was recorded in tank 206 on 23 June 1996. The maximum ready storage temperature recorded was 117 degrees Fahrenheit in tank 224 on 23 June 1996. The maximum hull storage temperature recorded was 108 degrees Fahrenheit in tank 206 on 24 June 1996 and tank 221 on 10 July 1996 (see part 6 for additional temperature data obtained at Fort Stewart).

The ambient humidity at Fort Stewart ranged from 14 to 100 percent. Readings of 100 percent were obtained during each month. Hull storage readings ranged from 37 to 100 percent, with the hull storage of five of the six tanks reaching 100 percent humidity. The remaining tank, tank 210, had a maximum hull storage humidity reading of 83 percent.

Tank 210 was the only instrumented tank that did not show evidence of standing water in the hull storage area. Semiready storage readings ranged from 21 to 100 percent, with four of the six instrumented tanks reaching 100 percent humidity. The remaining tanks, tanks 210 and 213, had maximum ready storage readings of 88 and 83 percent, respectively. Ready storage humidity readings ranged from 29 to 100 percent, with three of the six instrumented tanks reaching 100 percent humidity. The remaining three tanks (tanks 210, 213, and 219) had maximum humidity readings of 79, 93, and 90 percent, respectively. No standing water was noted in the semiready or ready storage areas of any of the instrumented tanks (for additional humidity distribution data, see part 6).

From 24 June - 16 December 1996, four M1A1 tanks were instrumented at Taborfalva Training Area, Hungary. During this timeframe, the ambient temperature ranged from

20 degrees Fahrenheit to 93 degrees Fahrenheit. The maximum semiready storage temperature reading of 98 degrees Fahrenheit was recorded in tank 301 on 8 July 1996. The maximum ready storage temperature of 107 degrees Fahrenheit was also recorded in tank 301 on 8 July 1996. The maximum recorded hull storage temperature of 105 degrees Fahrenheit occurred in tank 301 on 4 July 1996.

The ambient humidity at Taborfalva Training Area ranged from 20 to 100 percent.


Readings of 100 percent were obtained during each month of instrumentation. Hull storage readings ranged from 36 to 100 percent with three of the four instrumented tanks recording maximum readings of 100 percent. The remaining tank, tank 304, had a maximum recorded reading of 93 percent. Semiready storage readings ranged from 36 to 100 percent with the semiready storage of each instrumented tank reaching 100 percent for a period of time. The ready storage humidity readings ranged from 34 to 100 percent, with only tank 312 reaching 100 percent humidity. Each of the remaining three instrumented tanks had maximum humidity readings in the ready storage area in excess of 75 percent. Additional details for the temperature and humidity data obtained in Hungary are located in part 6.

From 27 June - 20 August 1996, three M1A1 tanks at Camp Gary Owen, South Korea were each equipped with three data loggers. This timeframe is referred to as "Setup No. 1." Instead of replacing the removed data loggers, four sets of three data loggers were placed in four different M1A1 tanks, referred to as "Setup No. 2." Monitoring of these four tanks continued until the termination of the program on 18 December 1996. No ambient conditions at this location were obtained during this timeframe. Ambient conditions from AD-2 were used for data analysis. During this timeframe, ambient temperature conditions ranged from 14 to 100 degrees Fahrenheit. The maximum semiready storage temperature reading was 110 degrees Fahrenheit in tank A-42 on 1 August 1996. The maximum ready storage temperature was


104 degrees Fahrenheit in tank C-33 on 21 August 1996. The maximum hull storage temperature was 104 degrees Fahrenheit in tank C-33 on 21 August 1996.

The ambient humidity at AD-2 ranged from 15 to 100 percent. Readings of 100 percent were obtained during each month of instrumentation. Hull storage readings ranged from 33 to 100 percent with three of the four instrumented tanks in Setup No. 2 having readings of 100 percent. The remaining tank, tank A-14, had a maximum hull storage humidity reading of 76 percent. Semiready storage humidity readings ranged from 36 to 90 percent, with the semiready storage of six of the seven tanks that were instrumented providing readings in excess of 78 percent at a period of time. The ready storage humidity readings ranged from 28 to 98 percent, with the minimum peak humidity reading of any instrumented tank being 79 percent. Additional details for the temperature and humidity data obtained in South Korea are located in part 6.

PHOTOGRAPHS



U.S. ARMY DEFESE AMMUNITION CENTER




U.S. ARMY DEFESE AMMUNITION CENTER

PHOTO NO. A0317-SCN-96-155-3043. This photograph shows an ACR data logger located in the semiready rack of an M1A1 tank.




U.S. ARMY DEFESE AMMUNITION CENTER

PHOTO NO. AO317-SCN-96-155-3045. This photograph shows the ready rack of an M1A1 tank. An ACR data logger is located in the top right of the compartment.



U.S. ARMY DEFESE AMMUNITION CENTER

PHOTO NO. A0317-SCN-96-155-3040. This photograph shows an ACR data logger located in the hull rack of an M1A1 tank.



U.S. ARMY DEFESE AMMUNITION CENTER

PHOTO NO. AO317-SCN-96-155-3055. This photograph shows the weather station installed at Fort Stewart.


GRAPHS

FORT STEWART DATA


FT. STEWART M1A1 TANK MONITORING DATA

AMBIENT	JUNE	JULY		SEPTEMBER	OCTOBER
High Temperature Low Temperature	101 60	101 71	96 68	96 5 8	89 44
High Humidity Low Humidity	100 23	100 26	100 28	100 15	100 14
TANK 206					
SEMIREADY					404
High Temperature Low Temperature	112 68	102 76	96 76	103 72	101 56
High Humidity	94 32	68 45	61 47	100 52	81 57
Low Humidity READY					
High Temperature Low Temperature	115 68	117 75	111 75	97 72	98 55
High Humidity	92	63	55	100	100
Low Humidity HULL	31	42	44	52	90
High Temperature	108 64	98 77	98 76	95 70	89 56
Low Temperature High Humidity	100	100	100	100	65
Low Humidity	50	65	79	45	45
TANK 210					
SEMIREADY High Temperature	108	100	NA	96	87
Low Temperature	69 81	85 67	NA NA	7 7 87	60 88
High Humidity Low Humidity	36	61	NA	77	63
READY High Temperature	116	113	108	110	94
Low Temperature	61	75	73	72	55
High Humidity Low Humidity	79 29	60 42	55 43	55 43	55 43
HULL		99	89	89	85
High Temperature Low Temperature	106 70	77	74	73	56
High Humidity Low Humidity	50 37	83 42	80 74	80 49	57 49
	0.				
TANK 213 SEMIREADY					
High Temperature Low Temperature	98 69	101 77	93 75	89 72	84 55
High Humidity	81	83	84	88	87
Low Humidity READY	60	62	70	51	44
High Temperature Low Temperature	107 69	113 76	104 73	98 68	92 54
High Humidity	83	67	61	93	78
Low Humidity HULL	54	37	40	66	58
High Temperature	107 69	107 84	107 78	101 70	87 55
Low Temperature High Humidity	100	100	87	100	100
Low Humidity	86	53	84	75	87
TANK 219					
SEMIREADY High Temperature	101	104	97	104	93
Low Temperature High Humidity	68 100	75 85	74 90	70 92	55 83
Low Humidity	47	55	69	49	55
READY High Temperature	111	112	NA	108	93
Low Temperature High Humidity	71 90	85 67	NA NA	70 88	56 77
Low Humidity	39	38	NA	57	55
HULL High Temperature	101	93	NA	98	84
Low Temperature High Humidity	71 100	82 100	NA NA	69 100	54 97
Low Humidity	84	52	NA	66	64
TANK 221					
SEMIREADY High Temperature	99	104	95	95	85
High Temperature Low Temperature	69	77	74	72	58
High Humidity Low Humidity	100 40	95 45	59 42	92 31	92 21
READY			103	110	98
High Temperature Low Temperature	111 68	116 70	75	70	57
High Humidity Low Humidity	100 42	100 44	94 49	100 39	84 39
HULL		108			97
High Temperature Low Temperature	98 70	76	93 75	92 73	65
High Humidity	97 59	100 85	100 94	100 54	100 74
Low Humidity	53	-	04	04	
TANK 224 SEMIREADY					
High Temperature	102 69	90 85	NA NA	95 68	85 54
Low Temperature High Humidity	100	50	49	100	100
Low Humidity READY	73	44	44	43	69
High Temperature	117 70	109 75	110 73	102 68	9 4 53
Low Temperature High Humidity	100	94	92	90	85
Low Humidity HULL	64	71	69	75	68
High Temperature	93	106	88	81	NA NA
Low Temperature High Humidity	70 97	76 97	74 97	73 100	NA
Low Humidity	59	56	84	94	NA

1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 206




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 206




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 206







1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 206




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 206




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 206



1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 206




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 206




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 210







1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 210




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 210







1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 210




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 210




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 210




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 210




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 213



1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 213




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 213





1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 213






1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 213







1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 213




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 213




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 219







1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 219



1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 219




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 219




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 219







1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 219




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 219







1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 221



1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 221



1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 221




SEMIREADY


READY


AMBIENT

1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 221




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 221






1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 221







1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 221




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 221




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 224




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 224






1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 224









1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 224







1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 224





1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 224




1996 M1A1 Tank Evaluation Ft. Stewart, Georgia Tank 224














Ft. Stewart, Tank 224











ದು Semiready ಜಾ Ready

E.: Hull


Ambient

con Ambient
cos Semiready
cos Ready
Lus Hull

gg Semiready

rza Ready co Hull

🖛 Ambient



1500

Number of Occurences

ඎ Semiready ඎ Ready

> 70-80 Humidity

60-70

50-60


40-50


& Ambient


Ft. Stewart, Tank 224


September, 1996


3000 2500 2000











🖾 Semiready 🖾 Ready

InH C

100

Mag Ambient

Raa Ambient Est Semiready Raa Ready

InH Co


en Ambient en Semiready en Ready

100


HUNGARY DATA

HUNGARY M1A1 TANK MONITORING DATA


AMBIENT High Temperature Low Temperature	JUNE NA NA	JULY 93 42	AUGUST 90 45	SEPTEMBER 74 36 100	OCTOBER 72 24 100	NOVEMBER 70 24 100	DECEMBER 47 20 100
High Humidity Low Humidity	NA NA	100 25	100 20	37	38	34	59
TANK 301 SEMIREADY	00	00	0.4	77	70	64	46
High Temperature Low Temperature	88 60	98 58	94 59	77 46	70 37	64 31	46 30
High Humidity	100	100	100	100	100	67	66
Low Humidity	54	85	36	56	52	53	55
READY High Temperature	89	107	101	81	75	63	51
Low Temperature	60	57	58	45	35	31	30
High Humidity	94	95	96	66	75 50	76 57	76 50
Low Humidity HULL	47	59	35	51	52	57	56
High Temperature	77	105	98	93	83	64	57
Low Temperature	63	60	62	49	35	34	31
High Humidity Low Humidity	100 47	100 76	100 36	100 94	100 59	68 58	69 55
					-		
TANK 304 SEMIREADY				,			
High Temperature	89	95	93	79	72	63	44
Low Temperature	60	58	58	48	37	33	28
High Humidity Low Humidity	100 52	100 69	100 43	75 49	70 50	63 49	59 4 9
READY	32			.0			
High Temperature	93	102	101	85	74 37	77 34	52 29
Low Temperature High Humidity	59 92	57 94	5 7	48 84	70	62	62 62
Low Humidity	52	71	49	43	43	41	48
HULL High Temperature	98	89	96	87	77	58	52
Low Temperature	63	60	58	48	39	34	29
High Humidity	91	90	88	73	73	65	65
Low Humidity	48	76	46	48	51	50	51
TANK 306 SEMIREADY							
High Temperature	83	94	91	76	74	65	45
Low Temperature	60 61	58 65	59 67	48 66	36 73	33 83	27 75
High Humidity Low Humidity	61 51	65 52	67 39	45	73 46	47	33
READY							
High Temperature Low Temperature	89 59	104 57	97 59	83 47	77 34	70 31	46 27
High Humidity	59	62	67	65	78	83	81
Low Humidity	47	44	40	42	41	40	51
HULL High Temperature	83	100	104	89	80	75	57
Low Temperature	63	62	68	53	35	34	29
High Humidity Low Humidity	100 50	100 81	100 37	100 61	100 68	94 84	92 85
Low Humaity	30	01	31	01	00	04	00
TANK 312							
SEMIREADY High Temperature	89	95	94	81	74	67	44
Low Temperature	59	58	58	46	39	29	28
High Humidity Low Humidity	99 31	99 59	100 35	79 53	97 54	94 70	92 70
READY	31	39	55	55	04	70	70
High Temperature	91	99	100 56	82	76 36	66 29	42 27
Low Temperature High Humidity	60 94	56 100	97	46 82	36 100	29 97	27 94
Low Humidity	48	54	34	50	46	62	73
HULL High Temperature	94	93	102	97	89	73	42
Low Temperature	64	60	59	56	38	32	29
High Humidity	100	100	100	100	100	100	100
Low Humidity	47	89	37	67	51	90	94















Julian Date


SEMIREADY

READY

AMBIENT








SEMIREADY


READY


AMBIENT


1996 M1A1 Tank Evaluation




Julian Date












































1996 M1A1 Tank Evaluation

























































Ra Ambient
En Semiready
En Ready

7

spuesnoul

Hungary, Tank 306

100


90-100


0-80 80-90 Humidity


60-70

90-09

0







Thousands

Number of Occurences

Semiready
 Ready
 Hull


30-40 40-50 50-60 60-70 70-80 80-90 90-100 Humidity


0


88 Ambient

Hungary, Tank 306

August, 1996







c: Semiready M Ambient

Hungary, Tank 306 September, 1996


m Ready


100


70-80 80-90 90-100 Humidity

50.60

40-50







Number of Occurences
Thousands

⊠ Semiready

iss Ready iss Hull


> 30-40 40-50 50-60 60-70 70-80 80-90 90-10 Humidity


0


88 Ambient


Hungary, Tank 306


2

















® Ambient ™ Semiready

Hungary, Tank 306

December, 1996

2000

1500

1000

Number of Occurences

is Ready □ Hull

100


70-80 80-90 Humidity


02-09

50-60

0

200







SOUTH KOREA SETUP NO. 1 DATA

SOUTH KOREA M1A1 TANK MONITORING DATA SETUP #1 (JUNE 27 - AUGUST 20)


AMBIENT High Temperature Low Temperature High Humidity Low Humidity	JUNE	JULY	AUGUST
	84	97	100
	61	59	66
	100	100	100
	70	45	28
TANK A-24 SEMIREADY High Temperature Low Temperature High Humidity Low Humidity READY	75	83	93
	68	68	84
	90	90	90
	85	72	78
High Temperature Low Temperature High Humidity Low Humidity HULL	75	83	94
	68	68	85
	88	88	88
	83	79	77
High Temperature	NA	NA	NA
Low Temperature	NA	NA	NA
High Humidity	NA	NA	NA
Low Humidity	NA	NA	NA
TANK A-42 SEMIREADY High Temperature Low Temperature High Humidity Low Humidity READY	80	97	110
	67	66	83
	54	58	NA
	46	48	NA
High Temperature Low Temperature High Humidity Low Humidity HULL	NA NA NA NA	NA NA NA	NA NA NA
High Temperature Low Temperature High Humidity Low Humidity	75	85	91
	68	67	81
	59	63	NA
	56	51	NA
TANK A-44 SEMIREADY High Temperature Low Temperature High Humidity Low Humidity READY	75	87	103
	68	67	83
	60	64	NA
	51	53	NA
High Temperature Low Temperature High Humidity Low Humidity HULL	NA NA NA NA	NA NA NA	NA NA NA NA
High Temperature	79	87	101
Low Temperature	68	68	83
High Humidity	64	68	NA
Low Humidity	56	56	NA

1996 M1A1 Tank Evaluation Camp Gary Owen, South Korea Tank A-24







1996 M1A1 Tank Evaluation Camp Gary Owen, South Korea Tank A-24










1996 M1A1 Tank Evaluation Camp Gary Owen, South Korea Tank A-42





1996 M1A1 Tank Evaluation Camp Gary Owen, South Korea Tank A-42















1996 M1A1 Tank Evaluation Camp Gary Owen, South Korea Tank A-44





1996 M1A1 Tank Evaluation Camp Gary Owen, South Korea Tank A-44








SOUTH KOREA SETUP NO. 2 DATA


SOUTH KOREA M1A1 TANK MONITORING DATA SETUP #2 (AUGUST 20 - DECEMBER 18)


AMBIENT	AUGUST	SEPTEMBER		NOVEMBER	
High Temperature Low Temperature	97 63	87 48	80 29	67 20	59 14
High Humidity	100	100	100	100	100
Low Humidity	33	30	15	19	24
TANK A-14					
SEMIREADY High Temperature	94	82	90	58	63
Low Temperature	65	68	38	24	15
High Humidity	54 45	53 46	77 37	87 50	66 35
Low Humidity READY	40	40	31	50	33
High Temperature	96	83	85	58	63
Low Temperature High Humidity	65 52	68 50	38 60	26 80	15 64
Low Humidity	43	46	35	50	31
HULL High Tomperature	95	81	83	65	67
High Temperature Low Temperature	65	70	40	27	16
High Humidity	71	76	67	70	70
Low Humidity	49	63	33	53	32
TANK B-11					
SEMIREADY High Temperature	96	83	83	NA	NA
Low Temperature	65	70	50	NA	NA
High Humidity Low Humidity	62 45	62 50	61 43	NA NA	NA NA
READY	45	30	43	INA	N/S
High Temperature	96	83	79	60	64
Low Temperature High Humidity	65 61	70 60	49 66	23 98	14 72
Low Humidity	44	49	40	53	29
HULL High Temperature	97	73	93	65	67
Low Temperature	66	68	44	27	16
High Humidity Low Humidity	81 44	72 46	100 43	100 69	92 37
Low Humany	74	40	43	03	37
TANK C-33 SEMIREADY					
High Temperature	102	90	79	60	64
Low Temperature	65 75	68 73	40 76	23 79	14 56
High Humidity Low Humidity	40	51	36	44	34
READY	404	0.4	0.4	00	0.5
High Temperature Low Temperature	104 65	94 68	84 38	60 23	65 14
High Humidity	80	75	76	75	64
Low Humidity HULL	44	51	39	44	28
High Temperature	104	85	81	NA	NA
Low Temperature High Humidity	67 100	69 100	47 100	NA NA	NA NA
Low Humidity	42	92	39	NA	NA
TANK D-31					
SEMIREADY					
High Temperature Low Temperature	96 68	98 70	82 40	61 24	54 15
High Humidity	54	78	81	62	62
Low Humidity	46	50	42	39	42
READY High Temperature	97	94	93	60	54
Low Temperature	65	72	38	21	13
High Humidity Low Humidity	79 44	52 44	76 36	76 49	66 48
HULL					
High Temperature Low Temperature	94 65	91 70	82 41	67 2 9	72 19
High Humidity	53	53	100	100	92
Low Humidity	45	45	39	71	47














1996 M1A1 Tank Evaluation Camp Gary Owen, South Korea Tank A-14












Camp Gary Owen, South Korea 1996 M1A1 Tank Evaluation Tank B-11





Ambient






E H





Camp Gary Owen, South Korea Tank B-11 1996 M1A1 Tank Evaluation

Ambient



Ready

E H


305

300


295

Julian Date


1996 M1A1 Tank Evaluation Camp Gary Owen, South Korea Tank B-11




1996 M1A1 Tank Evaluation




1996 M1A1 Tank Evaluation Camp Gary Owen, South Korea Tank B-11










1996 M1A1 Tank Evaluation Camp Gary Owen, South Korea Tank C-33




1996 M1A1 Tank Evaluation Camp Gary Owen, South Korea Tank C-33













1996 M1A1 Tank Evaluation Camp Gary Owen, South Korea Tank C-33








1996 M1A1 Tank Evaluation Camp Gary Owen, South Korea Tank C-33
















1996 M1A1 Tank Evaluation Camp Gary Owen, South Korea Tank D-31





1996 M1A1 Tank Evaluation Camp Gary Owen, South Korea Tank D-31

